

Road distance m	Tunnel entrance	Rock type	Sampling date	Staff	Other	Box Nr.
3734	Esksjörður	Altered basalt with a lot of amygdale fillings	22.7.2014	Christa/Martin-Ófeigur		6
8855	Nordfjörður	Basalt with microtectonic structures	22.7.2014	Christa/Martin-Ófeigur		8
3390	Esksjörður	Kargi 2 Stueck	6.8.2014	Christa-Ófeigur		1
3380	Esksjörður	Rauður kargi	6.8.2014	Christa-Ófeigur		1
3335	Esksjörður	Kargi	6.8.2014	Christa-Ófeigur		1
3290	Esksjörður	Gangur, basalt	6.8.2014	Christa-Ófeigur		1
3260	Esksjörður	Basalt	6.8.2014	Christa-Ófeigur		2
3205	Esksjörður	Basalt/kargi	6.8.2014	Christa-Ófeigur		2
3180	Esksjörður	Kargi	6.8.2014	Christa-Ófeigur		2
3110	Esksjörður	Basalt	6.8.2014	Christa-Ófeigur		2
2920	Esksjörður	Setlag rauzt	19.9.2014	Christa-Ófeigur		3
2812	Esksjörður	Basalt 2, Sýlla og hraunlag	19.9.2014	Christa-Ófeigur		3
2080	Esksjörður	Setlag rauzt (í plastpoka)	19.9.2014	Christa-Ófeigur		3
2665	Esksjörður	Sýlla basalt	19.9.2014	Christa-Ófeigur		3
2568	Esksjörður	Basalt	19.9.2014	Christa-Ófeigur		3
2419	Esksjörður	Setlag í plastpoka	19.9.2014	Christa-Ófeigur		3
2365	Esksjörður	Basalt	19.9.2014	Christa-Ófeigur		3
2272	Esksjörður	Basalt	19.9.2014	Christa-Ófeigur		3
2230	Esksjörður	Basalt	19.9.2014	Christa-Ófeigur		3
2190	Esksjörður	Kargaberg basalt	19.9.2014	Christa-Ófeigur		3
2167	Esksjörður	Setlag rauzt "bloody layer"	19.9.2014	Christa-Ófeigur		3
2118	Esksjörður	Kargaberg basalt	19.9.2014	Christa-Ófeigur		3
9095	Fannardalur	Basalt	19.11.2014	Martin-Birgir		4
9118	Fannardalur	Pyroclastic rock	19.11.2014	Martin-Birgir		4
9150	Fannardalur	Sedimentary interbed	19.11.2014	Martin-Birgir		4
9211	Fannardalur	red sedimentary interbed	19.11.2014	Martin-Birgir		4
9230	Fannardalur	Ignimbrite	19.11.2014	Martin-Birgir		4
9226	Fannardalur	red sedimentary interbed/overlying ignimbrite?	19.11.2014	Martin-Birgir		4
8450	Fannardalur	Ignimbrite, welded tuff	19.11.2014	HNT		4 Fell down when concrete broke
9259	Fannardalur	Kargabasalt með holufylling kvars	5.12.2014	Martin-Birgir		5
9272	Fannardalur	red sedimentary interbed	5.12.2014	Martin-Birgir		5
9299	Fannardalur	Kargaberg, basalt	5.12.2014	Martin-Birgir		5
9333	Fannardalur	??? Unclear signature on draft profile	5.12.2014	Martin-Birgir		5
9350	Fannardalur	red sedimentary interbed	5.12.2014	Martin-Birgir		5
9364	Fannardalur	Kargaberg, basalt	5.12.2014	Martin-Birgir		5
9480	Fannardalur	Massif basalt	5.12.2014	Martin-Birgir		5
9559	Fannardalur	Kargaberg, basalt	5.12.2014	Martin-Birgir		5
9589	Fannardalur	Massif basalt	5.12.2014	Martin-Birgir	5 9530 vantar rauð millag, fannst ekki	
9597	Fannardalur	Rauð millag??	5.12.2014	Martin-Birgir	5 Red rock, uncertain if middle layer	
9610	Fannardalur	Kargaberg, basalt	5.12.2014	Martin-Birgir		
9625	Fannardalur	Massif basalt	5.12.2014	Martin-Birgir		Northern entrance of tunnel
4075	Esksjörður	Setlag í poka	16.1.2015	Christa-Ófeigur		6
4020	Esksjörður	Basalt	16.1.2015	Christa-Ófeigur		6
3900	Esksjörður	Basalt dyke	16.1.2015	Christa-Ófeigur		6
3800	Esksjörður	Redish basalt	16.1.2015	Christa-Ófeigur		6
3734	Esksjörður	altered basalt with a lot of amygdale fillings	22.7.2014	Christa/Martin-Ófeigur		6
3648	Esksjörður	Basalt	16.1.2015	Christa-Ófeigur		6
3580	Esksjörður	Scoria Basalt lots of cavity fillings	16.1.2015	Christa-Ófeigur		6
3453	Esksjörður	Basalt	16.1.2015	Christa-Ófeigur		6
4091	Esksjörður	Basalt? Og eitthvað annað	27.2.2015	Martin-Börny		7 Gangur ekki greinilegur (var steypt yfir, kannski ekki bedrock)
4135	Esksjörður	Basalt	27.2.2015	Martin-Börny		7
4140	Esksjörður	Tuff/andsteinn (littar steinar)	27.2.2015	Martin-Börny		7
4196	Esksjörður	(kargi) basalt	27.2.2015	Martin-Börny		7
4200	Esksjörður	Minerals (mesóliðh??, mordenit)	27.2.2015	Martin-Börny		7
9070	Fannardalur	Basalt	8.4.2015	Christa-Börny		8
9050	Fannardalur	Basalt gangur?	8.4.2015	Christa-Börny		8
9015	Fannardalur	Basalt	8.4.2015	Christa-Börny		8
8957	Fannardalur	Basalt	8.4.2015	Christa-Börny		8
8857	Fannardalur	Setlag	8.4.2015	Christa-Börny		8
8855	Nordfjörður	Basalt with microtectonic structures	22.7.2014	Christa/Martin-Ófeigur		8
8766	Fannardalur	Setlag	8.4.2015	Christa-Börny		8
8740	Fannardalur	?	8.4.2015	Christa-Börny		8
8729	Fannardalur	Ignimbrit?	8.4.2015	Christa-Börny		8
8648	Fannardalur	Basalt	8.4.2015	Christa-Börny		8
8560	Fannardalur	Basalt	8.4.2015	Christa-Börny		8
8515	Fannardalur	Basalt, gangur	8.4.2015	Christa-Börny		8
8503	Fannardalur	Basalt	8.4.2015	Christa-Börny		8
8479	Fannardalur	Ignimbrit	8.4.2015	Christa-Börny		8
8450	Fannardalur	Ignimbrite, welded tuff	19.11.2014	HNT		9 Fell down when concrete broke
8435	Fannardalur	Ignimbrit	8.4.2015	Christa-Börny		9
8417	Fannardalur	Ignimbrit	8.4.2015	Christa-Börny		9
8403	Fannardalur	Basalt, not bedrock, gangur?	8.4.2015	Christa-Börny		9
8395	Fannardalur	Basalt	8.4.2015	Christa-Börny		9
8385	Fannardalur	Basalt, not bedrock, gangur?	8.4.2015	Christa-Börny		9
8377	Fannardalur	Basalt, not bedrock, gangur?	8.4.2015	Christa-Börny		9
8330	Fannardalur	Basalt	8.4.2015	Christa-Börny		9
8305	Fannardalur	Basalt gangur, sama og 8290	8.4.2015	Christa-Börny		9
8290	Fannardalur	Basalt gangur, sama og 8305	8.4.2015	Christa-Börny		9
8238	Fannardalur	Ignimbrit	8.4.2015	Christa-Börny		9
8200	Fannardalur	Basalt	17.4.2015	Martin-Börny		10
8170	Fannardalur	Leiðsteinn ör millag	17.4.2015	Martin-Börny		10
8158	Fannardalur	Basalt, "bruchig, brösmeliq"	17.4.2015	Martin-Börny		10 inniheldur áðugavert holufylling
8128	Fannardalur	Basalt, berggangur	17.4.2015	Martin-Börny		10 Dyke
8070	Fannardalur	Basalt	17.4.2015	Martin-Börny		10
8036	Fannardalur	Basalt, berggangur?	17.4.2015	Martin-Börny		10
7985	Fannardalur	Basalt	17.4.2015	Martin-Börny		10
7905	Fannardalur	Kargabasalt	17.4.2015	Martin-Börny		10
7828	Fannardalur	Basalt	17.4.2015	Martin-Börny		10
7797	Fannardalur	Kargabasalt	17.4.2015	Martin-Börny		10
7780	Fannardalur	Basalt, holufyllingarkit	17.4.2015	Martin-Börny		10 Holufyllingar mikið af grænum kólum (celandónite leið)
7768	Fannardalur	Basalt, berggangur	17.4.2015	Martin-Börny		10
7696	Fannardalur	Kargabasalt	17.4.2015	Martin-Börny		10
7650	Fannardalur	Basalt	17.4.2015	Martin-Börny		10
7637	Fannardalur	Kargabasalt	17.4.2015	Martin-Börny		10
7578	Fannardalur	Basalt með útfyllingum	8.5.2015	Christa-Börny		11
7520	Fannardalur	Basalt, gangur, lítið sýni	8.5.2015	Christa-Börny		11
7507	Fannardalur	Basalt	8.5.2015	Christa-Börny		11
7437	Fannardalur	Basalt porous	8.5.2015	Christa-Börny		11
7408	Fannardalur	Basalt og útfellingar: kvars, seólitar, seladónite	8.5.2015	Christa-Börny		11 Ljósmyndir, nice outcrop, two big samples extra
7408,5	Fannardalur	Zenitadrulla	8.5.2015	Christa-Börny		11 Ljósmynd
7368	Fannardalur	Basalt	8.5.2015	Christa-Börny		11

